

FIRE HYDRANT TESTING AND INSPECTION COSTS

	Price ex GST
Inspection Costs :	
Hydrant per head	\$ 10.00
<hr/>	
Booster assembly per head (includes hydrants and booster connection point)	\$ 10.00
<hr/>	
Yearly flow check (or three yearly pre 2004) *	\$ 515.00
<hr/>	
Five yearly (or six yearly pre 2004) * PLUS \$68.00 per washer to be changed (as per table 4.4.4 item 4.7)	\$ 1,500.00
<hr/>	
All servicing is conducted in accordance with : <i>AS 1851-2012: Routine service of fire protection systems and equipment</i>	
Other plumbing services :	
Supply and install new fire hose reel Note : assumes area is clear with good access for plumber	\$ 630.00
<hr/>	
ROV* fire services water supply tank inspection**	\$ 800.00
Fire services water supply tank clean**	\$ 6,500.00
* Pricing is per zone	
** Remotely Operated Vehicle	
*** subject to tank age and condition	
Prices exclude GST	